

STATUSJET

2008 Hawker 900 XP



TT 3310.2 Landings 2008

New Paint 2019
New interior 2019
ADS B out
Engines on MSP Gold
APU on MSP Gold
CASP Avionics program



Primary Comparison Metrics

Damage:	No
Damage Notes:	None

Number of Engines:	2	Engine Maintenance Plan:	MSP Gold
Engine Make / Model:	HNYWL TFE731-50R-1H		
Engine Notes:	EICAS, HSI Due/OH 3000Hr HSI		

Maintenance Program:	NULL	Maint. Tracking Srvc:	Yes
Inspection Notes:	Landing Gear Completed 2019		
Maintenance Notes:			

Avionics - General			
Avionics - Navigation			
NAV:		FDS:	COL FGC 3000
Auto Pilot:	COL FGC 3000	ADF:	COL NAV 4000
EFIS:	COL PRO LINE 21 4 TUBE	FMS:	2 COL FMS 6000
Avionics - Data			
ALT:	2 COL ALT 4000	CVR:	UNIVERSAL CVR 120
ADC:	2 COL ADC 3000	DME:	2 COL DME 4000
FDR:	L3 88	GPS:	2 COL GPS 4000S
Avionics - Communications			
SATCOM:	AIRCELL ST 3100	COMM:	2 COL VHF 4000
HFCOMM:	COL HF 9000/SELCAL		
Avionics - Traffic			

TCAS System Name:	COL TTR 4000	TCAS Type:	II W/7.1
Mode:	S	TRANSPONDER:	2 COL TDR 94D
Avionics - Data Display			
MFD:		HUD:	
Avionics - Terrain			
GPWS:		EGPWS:	2 OCM 3100
Avionics - Weather			
RADAR:	COL RTA 858 TURB	STORMSCOPE:	
APU Type:	HNYWL 36 150W	APU Plan:	MSP
APU TSN:			
RVSM:	Yes	COMS:	
ADS-B:	Compliant		
Configuration:	EXECUTIVE	Interior:	
Color:		Date:	
Long Range O2:	NULL	Passengers:	7
Super Soundproofing:	Yes		
Interior Notes:	Seven (7) Passenger Configuration With Five Place Executive Club Arrangement In The Main Cabin And Two Place Belted Divan, Lavatory Seat Rated For Take-Off And Landings Along With An Observers Jump Seat, Aft Flushing Toilet And Vanity Cabinet, Airshow 410/4000 w/2 15" Monitors, DVD, Therapeutic Oxygen, 2 Rear Storage Closets		
Exterior Notes:	Boom Beam Taxi/Landing Light System, Logo Lights, Pulselite with TCAS Interface		
Additional Notes:	Artex C406N ELT, Dual FSI-5010 File Server, IFIS 5000 Paperless, Rosen Sun Visors,		

